ECS Configuration Change Request Page 1 of **Pages** CCR No. 96-0149 **Logged Date Request Type** 2/20/96 Rev. **CCR Priority** Routine Urgent X Emergency **Change Class Affected Release** II Title Infrastructure / Mini-DAAC Transfer in EDF **Documents Affected** Source Nos (RID, NCR, etc.) or Tech Reference N/A N/A RTM Change Start New Baseline **Problem** When transferring Sybase data base from Calvin to DPR-EDF-8, there was a problem of data corruption and timeouts. This data transfer involved moving files Osaka and Kyoto on the infrastructure side of the network to DPR-EDF-8 in the Mini-DAAC. It is believed that this problem is related to the FDDI switch, where the interim solution is to set the transmitting MTUs to 1500... **Proposed Solution** Change MTU settings to 1500 on all EDF machines on FDDI as interim solution. (See Attachment describing test results). Incorporate Alantec fixes (i.e. s/w short term fix) and final solution to FDDI switch problem and verify via testing. **Alternative Solution:** Provide an SGI Challenge DM machine (e.g.MSFC) on infrastructure side of network, when available. **Impact Analysis:** Organizations Affected: BOO Contracts **ESO** M&O Rel. A X Rel. B Rel. IR1 MRS X SMO Subconts Other Cost: None Small Medium Large (Not exceeding \$100,000) (\$100,000 to \$500,000) (Over \$500,000) Schedule: Other ASAP on interim solution None Additional LOC None Man-Months Materials Originator Harvey Privor Signature Date Office Manager Office MRS Les Wheeler Signature Date **Disposition** Approved Approved w/Comment Forward Disapproved Comments: Deferred 2/26 - Darryl W. is evaluation an HP patch, in parallel Alantec is working a s/w fix to the FDDI switch.

CM01JU95 ECS

Date

Signature

CCB Chairperson